



Air Force Fuels Quality Update

TEAM INSIGHT



Technical Division
Air Force Petroleum
Office
USAF



Charleston AFB SC

“Off-Spec Fuel Receipts”



- Apr 98; High PC, High DP'
 - Drove F/S Element Change-outs
- Aug 98; High PC, 3.0 Mg/l
- Feb 99; Water >20, PC 2.6 Mg/l
- Sept 99; PC, 3.3 Mg/l
- Dec 99; Water, >20



Charleston AFB SC (Cont.)

- Suspect Causes

- Leaky Geodesic Dome at DFSP Charleston
- Lack of Receipt F/S & Inadequate H2O Removal Abilities

- Corrective Actions To Date

- DESC Installed Filtration Between DFSP and Charleston AFB
 - DESC Initiated Corrective Action Against

Contractor

- DFSP Charleston Identified Facility

Upgrade/Repair Projects

- AF Testing 4th Edition API 1581 Elements
- DESC Installed 4th Edition API Elements in DFSP Filter



NELLIS AFB "JFTOT Failure" (Feb 99)

- Oct 98; Waiver Granted
 - Permitted Paramount to Add .2 Mg/l MDA
- Feb 99; Aircraft Sample Failed JFTOT
- Nellis Bulk/Hydrant Tanks Failed JFTOT
- Supporting DFSP Tank's Failed JFTOT
- 7.6M Gallons Affected by Failing JFTOT



JFTOT RESULTS

TEAM NISIT

Tube Rating
OK



Tube Rating Fails @
3A



NELLIS AFB

- Metals Analysis Performed by AFRL/Fuels
 - Disclosed Traces of Zinc, No Other Metals
- MDA Injected In Failing Inventories @ .2 Mg/l
 - Passed JFTOT After MDA Injection
- Jan 00; Reoccurred in Cal-Nev Tank
 - .2 Mg/l MDA Corrected Problem
- Apr 00; Reoccurred (Nellis, Cal-Nev, DFSP)
 - Again MDA Added @ .2 Mg/l to “Fix” Problem
- Sep 00; Reoccurred (Norwalk DFSP) TDR 4 Two Tanks
- DESC and SFTH Investigating/DESC hired CWB to Study



LANGLEY AFB


(Mar 99)

- Mar 99; Initial Barge Receipt Sample Failed PC
- QSR Responded/Operation Shut-down
- QSR Directed Resamples
 - Barge composite failed PC
 - Receipt line sample failed PC
- QSR Rejected Barge



LANGLEY AFB

TEAM NISL





LANGLEY AFB (CONT)

- Receipt Failures Continued from High PC
- Corrective Actions Attempted
 - Barge Cleaned
 - Increased QS During Vessel Loading
 - Light-loaded the Barge
 - Problems Continued
- Contractor Finally Defaults
- New Contract Awarded
 - Seemed to Remedy PC Problems
- Sept 00; PC Problems Recurring--Visible



TYNDALL AFB (DEC 99)

- Barge Receipt Samples Fail Water & PC Tests
 - Hay Pack Filter Operation Questionable
- 1,100 & 470 Gls H₂O Removed From Rec Tk's
- Intermediate Elements Changed 7-10 Days
- Corrective Actions to Date
 - SFTH and DEO-H Performed Site Visit
 - QS Increased During Load-out
 - Suspect Barge Removed From Service



Eareckson JFTOT Failures (Sept 99)

- Eareckson AFS
 - Barge composite sample failed JFTOT
 - Receipt tanks failed JFTOT
 - Entire Storage System Contaminated
 - Also contaminated King Salmon (common receipt vessel)
- Trace Metals Tests Performed at Cape Lab
 - Trace Metals Found
 - MDA Added--Post Samples Failed JFTOT
- Suspect Fuel (2.1M Gal) Consolidated



Eareckson JFTOT Failures


(CONT)

- Only 50K of On-Spec Product for A/C Support
 - NOTAM Issued Advising Limited Fuel Available
- Apr 00; Barge Rcpt Tank Failed JFTOT
 - Didn't Flush Barge Rcpt Line
 - Required MDA to Fix JFTOT
- Sept 00; Barge Rcpt Tank Failed JFTOT
 - Suspect Deicer Contamination
 - Threw All Fuel Off-Spec--No Fuel for A/C support
- Actions Underway to Remedy Eareckson
 - Filter October '00 Rcpt Through Faudi Filter
 - Push Rcpt into Newly Cleaned Tank



“Apple Jelly” Advisory

- Typical Analysis of Apple Jelly
 - 60% FSII, 38% H₂O & 2% Other
- DESC Initiated an Apple Jelly Tiger Team
 - Includes DEO & Service Rep's
 - AFRL Reported the Cause Was Attributed to Temperature/Phase Separation of FSII





Apple Jelly



Kunsan
AB

Minot AFB



Charleston
AFB

NAS
ceana





Apple Jelly “Things Learned”

- Fuel Loaded Clear & Bright--Arrives Cloudy
- Temp Variations Precede High DP's
 - Most Element Failures Occur @ 32 - 46 (F)???
- Manifests Itself in Low-points & Sumps
- API 1581 Elements Disarmed By Surfactants
 - Otis ANGB Experienced Some Success With Faudi Elements
- Expect/Report Reoccurrence This Winter




“Other Challenges”

- Ground Fuel Commingling
 - Operator Error
- Local Additive Injection
 - Over injecting SDA--Not Diluted to 9 Parts Fuel Before Injecting
 - Causes Some A/C Instrument Gages to “Roll”
 - Over Injecting/Improper Blending of FSII
 - Causes Corrosion Problems
 - Contributes to Formation of Apple Jelly



INFRASTRUCTURE CONCERNS “Filtration”

- ID Receipt Filtration Requirements
- Current Filters Disarmed by Surfactants:
 - Most Common Surfactants:
 - Static Dissipator Additive (SDA)
 - Corrosion Inhibitor
 - +100 Additive
- Filter Technology
 - API 1581 4th Edition Elements Available





NEW FILTRATION “TECHNOLOGY”

- API 1581, 4th Edition, M100 Class Elements
 - First Filters Tested w/Additized JP8 (+100 Too)
- Agreement with Facet
 - Side-by-Side 3rd Edition Vs. 4th Edition
 - Field Trial Being Conducted @ Charleston AFB SC
 - Further Expanded to Include Randolph AFB
- Otis ANGB (4th Ed, DESC Funded AJ Test)
- Burlington, VT (Unit Funded) AJ Location




FUTURE PLAN


- Three-Stage Filter Vessels at the Last Filtration Prior to the Aircraft Skin
- IP Monitors in Hydrant Servicing Equipment Being Considered
- API 1581, 4th Edition, M100 Elements In Fixed Systems



2-STAGE vs. 3-STAGE VESSELS



Separators & Monitors



Coalesce
rs



SUMMARY

- Recent Quality “Challenges”
- Infrastructure Concerns/Future Filtration
- Receiving Off-Spec Fuel
- Reporting Off-Spec Fuel

TH - YOUR "QUALITY" FUELS CONNECTION

Phone - (210) 925-4617, DSN 945-4617

Fax DSN 945-2025

Email = First.Last@Kelly.af.mil

Nov 00 Email will change to First.Last@lackland.af.mil